

Homemade Electric Locomotive Model and Track System



By A. E. ANDREW

PART I—The Motor

THE electric locomotive described may be constructed by boys having average mechanical ability and the necessary tools. However, in any piece of mechanical construction care must be taken to follow the instructions. The material required is inexpensive, and the pleasure derived from such a toy is well worth the time used in its construction.

The making of the outfit may be divided into three parts, the first of which is the motor; second, the truck, which is to carry the motor and the body of the car, and third, the track system upon which the engine is to operate. A side view of the locomotive is shown in Fig. 1.

The motor is of the series type, having its field and armature terminals connected to the source of electrical energy through a special reversing switch. By this means the rotation of the armature may be reversed to make the locomotive travel forward or backward. The armature and field are constructed of sheet-iron stampings, riveted together.

The detailed construction of the armature and its dimensions are shown in Fig. 2. The shaft upon which the armature core and commutator are to be rigidly mounted is made of a piece of steel rod, $\frac{3}{32}$ in. in diameter. A portion of this rod, $2\frac{1}{4}$ in. long, is threaded

with a fine thread, and two small brass, or iron, nuts are provided to fit it. The ends of the rod are turned down to a diameter of $\frac{1}{8}$ in. for a distance of $\frac{1}{8}$ in. These are to fit in the bearings that are to be made later.

Cut from thin sheet iron a sufficient number of disks, $1\frac{1}{8}$ in. in diameter, to make a pile exactly $\frac{5}{8}$ in. thick when they are securely clamped together. Drill a hole in the center of each of these disks, of such a size that they will slip on the shaft snugly. Remove the rough edges from the disks and see that they are flat. Cut two disks of the same size, from a piece of $\frac{1}{16}$ -in. spring brass, and drill a hole in the center of each, so that they will slip on the shaft. Place all these disks on the shaft, with the brass ones on the outside, and draw them up tightly with the nuts provided. Be sure to get the laminated core in the proper position on the shaft by observing the dimensions given in the illustration, Fig. 2.




FIG. 1
Side View of a Locomotive Designed to be Operated with Either End Forward

After the disks have been fastened, clamp the shaft in the chuck of a lathe and turn down the edges of all the disks so that they form a smooth

cylinder, $1\frac{1}{16}$ in. in diameter. Draw a circle on the side of one of the brass disks, $\frac{3}{32}$ in. from the edge, while the shaft is held in the chuck. Divide this circle into eight equal parts and make a center-punch mark at each division. Drill eight holes through the core lengthwise with a $\frac{3}{16}$ -in. drill. If the centers of the holes have been properly located, all the metal on the outside will be cut away, as shown in the end view, at the right in Fig. 2. The width of the gaps, F, G, H, etc., thus formed, should be about $\frac{1}{16}$ in. Smooth off all the edges with a fine file after the holes are drilled.

A cross-sectional view of the commutator is shown at the extreme left, Fig. 2. It is constructed as follows: Take a rod of copper or brass, $\frac{7}{8}$ in. in diameter, and $1\frac{1}{4}$ in. long; clamp one end in the chuck of a lathe. Turn the other end down to a diameter of $\frac{3}{4}$ in., and drill a $\frac{1}{2}$ -in. hole through it at the center. Cut away the metal from the end to form a disklike recess.

Cut off a disk, $\frac{5}{16}$ in. thick, measuring from the finished end, from the piece of stock. Place this disk in a chuck, with the unfinished end exposed, and cut away the metal in a dish form, as shown at B. Cut small slots, into which the ends of the wires used in winding are to be soldered, as shown at 1, 2, 3, etc., in the right-hand view of Fig. 2. Obtain two brass nuts, about $\frac{1}{4}$ in. in thickness, and turn their edges down so that they correspond in form to those shown at C and D. Divide the

points, in the rim of the disk. These cuts should be through the rim. Fill each of the slots with a piece of mica insulation.

Place one of the nuts on the shaft, and then a washer of mica insulation, shown by the heavy lines, near A and B; then the ring, a second piece of mica, and last the nut, C. The latter should be drawn up tightly, so that the insulation in the slots in the disk are opposite the drilled slots in the armature core, as shown in the right-hand view of Fig. 2. After the disk has been fastened securely, test it to learn whether it is insulated from the shaft. This is done by means of a battery and bell, connected in series, one terminal of the circuit being connected to the disk, and the other to the shaft. If the bell rings when these connections are made, the ring and shaft are not insulated. The disk must then be re-mounted, using new washers of mica insulation. Mica is used because of its ability to withstand a higher degree of heat than most other forms of insulation.

Each of the eight segments of the dished disk should be insulated from the others. Make a test to see if the adjacent commutator segments are insulated from each other, and also from the shaft. If the test indicates that any segment is electrically connected to another, or to the shaft, the commutator must be dismantled, and the trouble corrected.

The armature is now ready to be





FIG. 2
How the Armature Core is Made of Soft-Iron Disks for the Lamination, at the Left. Diagram for the Winding of the Armature Coils and Their Connection to the Commutator, at the Right



disk ring, just made, into eight equal parts, by lines drawn across it through the center. Cut eight slots at these

wound. Procure $\frac{1}{8}$ lb. of No. 26 gauge insulated copper wire. Insulate the shaft, at E, with several turns of thin

length, having a $\frac{1}{8}$ -in. hole drilled in one end to a depth of $\frac{7}{8}$ in., and a threaded hole in the other end, for a small machine screw, as shown in Fig. 7. Two holes are drilled and threaded in one side of each of these pieces. These holders are to be mounted, by means of screws, through the holes A, B, C, and D, Fig. 5. Each holder must be insulated from its support. The distance of the holder from its support should be such that the opening in its end is in the center of the commutator. The brushes are made of very fine copper gauze, rolled to form a rod. They

are made long enough to extend about $\frac{1}{2}$ in. into the holder, when they are resting on the commutator. A small spiral spring is placed in the holder, back of the end of the brush, and which will serve to keep the latter in contact with the commutator.

Temporary connections are made and the motor is tested with a six-volt battery. The construction of the motor may be modified as to the length of shaft, and other minor details, and may be used for other purposes by fitting it with pulleys, a countershaft, or other transmission devices.

Compliments of Robinson & Associates
www.grandscales.com www.7plusrailroader.com